




MODULE 3 NOTES

BY • WORLD'S OF AME •

Mass of proton = 1.67×10^{-27} kg

Mass of electron = 9.1×10^{-31} kg

Mass of electron = $\frac{1}{1836}$ of proton.



mass of proton is 1,837 times greater than electron.
proton weighs $\approx 1,845$ times as much as e^-

No. of protons and neutrons determines the overall weight of atom.

Magnetism: North seeking Pole / South seeking Pole.

(amp. righthand grip rule / corkscrew rule)
Corkscrew rule - direction of magnetic field (straight conductor)

Clasp rule - polarity

Biot savart law - strength of magnetic field.

Field force lines on thickness rather than length.

Magnetomotive force (like P.d)

$$\text{MMF} = I \times N \text{ (Amp. turns)}$$

unit

MMF is measured by
Symbol = F
Gilberts.

Permanent magnet Alnico.

Magnetising force (H): $H = \frac{\text{MMF}}{l} = \frac{I N}{l} \text{ (At/m)}$

Reluctance : Amp/web. (At/web)
turn.

Reluctance - opposition to becoming magnetised.

magnetic flux, $\phi = \frac{\text{MMF}}{\text{reluctance}}$ unit = weber

Permeability - It has no unit.

Permeability, $\mu = \frac{B}{H}$ - Flux density
magnetising force.

Types of magnetic materials:

Ferromagnetic material - Permeability greater than 1
(highly magnetic same direction) eg: Iron, nickel, cobalt.

Paramagnetic material - Permeability slightly greater than 1
(weakly magnetic same direction) eg: Platinum, manganese, chromium, Al.

Diamagnetic material: Permeability less than 1. Slightly diamagnetic
(weakly magnetic opposite direction) eg: bismuth.

✓ If force is more magnetic lines of force pass easily.

✓ Magnetic screen or shield: Magnetic lines of force does not go inside the instrument, it just pass through outer case of the instrument.

The point at which magnetic material loses its property is called Curie temperature.
Case of magnet: permanent 400°C

✓ Keeper bars are made of soft iron core.

Use keeper while magnet is stored, the magnetic flux will continuously circulate through the magnet and not leak off into space.

✓ Bar magnets should ^{always} be stored in pair with north and south pole placed together this provides path for magnetic flux without any flux leakage.

✓ Flat magnet depends on thickness and does not depend on length.

Ferrite - Nonmagnetic material that has ferromagnetic properties of iron.

no: of turn

Two parallel conductor:

- (i) Current in same direction - Field strength decrease of conductors attract
- (ii) Current in opposite direction } - Field strength increase conductors repel.

direction of current flow in conductor:

- (.) dot current flow towards you
- x current flow away from you.

Conventional flow (+)ve to (-)ve

Electron flow (-)ve to (+)ve.

Emf

$$E = \frac{\mathcal{E}}{Q}$$

E = potential difference in volts.

\mathcal{E} = energy expended or absorbed in joules

Q = charge measured in coulombs.

$$\text{Current } I = \frac{Q \text{ (charge) (C)}}{t \text{ (time) (s)}}$$

One coulomb equal to $\frac{6.28 \text{ billion billion electrons}}{6.28 \times 10^{18}}$

Velocity of charge is called drift velocity or average velocity.

Factors affecting resistance

1 mil is 1000 of an inch

1 square mil = 1.27 circular mil

1 circular mil = 0.785 square mil.

$$R = \frac{\rho l}{A}$$


$$G = \frac{1}{R}$$

Reciprocal of resistance is conductance

$$G = \frac{A \sigma}{l} \quad (\sigma = \frac{1}{\rho})$$

† Potentiometer - 3 terminals, 4 wires
controls voltage

Rheostat - 2 terminals, 2 wires
controls current



First & Second color band will never be gold or silver.


If third band is gold multiply 10%.


If third band is silver " 1%.

If there is no fourth band tolerance 20%.

Wire wound - control large amounts of current and have high power ratings.

Potentiometer is used to obtain a variable voltage from fixed voltage source to apply to an electrical load.

Capacitor  unit Farad.

Condenser - 

Factors affecting capacitor $C = k \frac{A}{d}$

No. of plate (n-1)

In capacitor → positive lead → long

It leads are same size - negative side diff. colour

Power, $P = \frac{\Sigma}{t}$

$P =$ power (W)
The rate of doing work.

$\Sigma =$ energy (Joule), $t =$ time (s)
amount of doing work

Resistance: (R) (Flow of charge opposition)

Unit ohm.

Factor, $R = \frac{\rho l}{A}$



Types of resistor:

- (i) wire wound resistor - Procelain material
↓
manganin wire ↓
Used for high precision, high power, high stability
- (ii) Ceramic metal - accurate resistance, high stability
under extreme temp.
- (iii) Metal film - ~~ex~~ excellent tolerance and temp. coeff
extremely reliable
- (iv) deposited carbon - lower current and closer tolerance.
- (v) Carbon composition - Produce electric noise, low cost
(stray)



Semiconductors - Thyristor, Thermistor, carbon.

Wheatstone bridge $\Rightarrow R_x = \frac{R_1}{R_2} \times R_3$

Resistivity - ohm meter

... ..


$$G = \frac{1}{R}$$

Reciprocal of resistance is conductance

$$G = \frac{A \rho \sigma}{l} \quad (\sigma = \frac{1}{\rho})$$

† Potentiometer - 3 terminals, 4 wires
controls voltage



Rheostat - 2 terminals, 2 wires
controls current



First & Second color band will never be gold or silver.
 If third band is gold multiply 10%
 If third band is silver " 1%
 If there is no fourth band tolerance 20%

Wire wound - control large amounts of current at have high power ratings.

Potentiometer is used to obtain a variable voltage from fixed voltage source to apply to an electrical load.

Capacitor  unit Farad.
 Condenser - 

Factors affecting capacitor $C = k \frac{A}{d}$

No. of plate (n-1)

In capacitor → positive lead → long

It leads are same size - negative side diff. colour


$$G = \frac{1}{R}$$

Reciprocal of resistance is conductance

$$G = \frac{A \sigma}{l} \quad (\sigma = \frac{1}{\rho})$$

† Potentiometer - 3 terminals, 4 wires
controls voltage

Rheostat - 2 terminals, 2 wires
controls current



First & Second color band will never be gold or silver.


If third band is gold multiply 10%.


If third band is silver " 1%.

If there is no fourth band tolerance 20%.

Wire wound - control large amounts of current & have high power ratings.

Potentiometer is used to obtain a variable voltage from fixed voltage source to apply to an electrical load.

Capacitor  unit Farad.

Condenser - 

Factors affecting capacitor $C = k \frac{A}{d}$

No. of plate (n-1)

In capacitor → positive lead → long

It leads are same size - negative side diff. colour

Energy stored in capacitor, $E = \frac{1}{2} CV^2$

Capacitor allows AC blocks DC
fully charge - open circuit; fully discharge - short circuit

Capacitor in DC - filter, short circuit.

Capacitor in AC - charging and discharging

in AC motor - phase shift.

unit of capacitor is Farad

* without decimal pico F (10^{-12})

* with decimal micro F (10^{-6})

Time constant
charge and discharge capacitors

$$\tau = RC$$

Time taken to charge 63% is 5τ
(Pg 10-51)

A parallel plate capacitor is made by stacking n equally spaced plates connected alternatively. If the capacitance b/w any two adjacent plates is C then the resultant capacitance $A_n = (n-1)C$

If n plates how many capacitor $(n-1)C$
if n capacitors " " plates $(n+1)C$

Troubles in capacitor:

- (i) Ohmmeter reads zero and stays there - short circuit
- (ii) It shows charging but final resistance less than normal } - leaky capacitor
- (iii) if the capacitor shows no charging but reads high resistance } - open circuit.

⊥

Hysteresis loss \propto frequency

eddy current loss \propto square of frequency.

in capacitance current will lead the voltage by 90°

Inductor is also known as choke

in inductance voltage will lead the current by 90°

Series:

- (i) Same current flows through all part of circuit.
- (ii) Different resistors have their individual voltage drop
- (iii) Voltage drops are additive
- (iv) Applied voltage equals the sum of different voltage drops
- (v) Resistors are additive
- (vi) Powers are additive.

Parallel:

- (i) Same voltage acts across all parts of the circuit
- (ii) Different resistors have their individual current
- (iii) Branch current are additive
- (iv) conductance are additive
- (v) Powers are additive.

dynamic electricity, it is in motion
static electricity, it is in rest.

Factors affecting capacitance

- * Distance b/w plates
- * Area of plate
- * Dielectric of capacitor.

Types of capacitor
electrolyte capacitor - Fast (withstand high volts)
mica capacitor (5000 micro farad to 0.02 micro farad)
Paper
ceramic - most used (withstand high freq)

Transformer:

The primary reason why open circuit test is performed on low voltage winding of the transformer. It draws sufficiently large load current for convenient reading.

Max. efficiency in transformer; $Cu \text{ loss} = \text{Iron loss}$

The main purpose of performing open circuit test on transformer is to measure core loss.

$$\frac{E_2}{E_1} = \frac{N_2}{N_1} = \frac{I_1}{I_2}$$

No load on transformer - magnetising current at no load

No load test on transformer is carried out to measure core loss (of iron when no load measure core loss)

Cu loss found in short circuit test

Hysteresis loss \propto freq Eddy current loss $\propto (\text{freq})^2$

Permittivity

While discussing phenomenon a certain property of medium is called permittivity.

Absolute permittivity, $\epsilon_0 = 8.85 \times 10^{-12} \text{ F/m}$

Relative permittivity, $\epsilon_r = \epsilon / \epsilon_0$

$$\epsilon = \epsilon_0 \epsilon_r \text{ F/m}$$

Cu loss, full load = $\frac{1}{4}$ no load, half load

$$\text{① } B = \frac{\phi}{\Delta}$$

3 main source - Batteries, thermocouple, photocells

phase angle (θ) - angular dist b/w voltage & current

Phase angle is the difference in degrees of rotation b/w two alternating current or voltage or b/w voltage & current.

Transformers are rated in kVA?

As seen w/loss of transformer depend I^2 , iron loss on voltage, Hence total transformer loss depends on VA and not on phase angle b/w voltage & current. i.e., it is independent of load power factor that is why trans. rated in kVA not in kW

Ideal transformer:

- i) winding has no resistance.
- ii) Core has no loss
- iii) Core has infinite permeability.

~~Transformer~~

Star and delta connection.

Star connection also known as wye connection

delta " " " mesh connection

delta connection

i) Line voltage = phase voltage

ii) line current = $\sqrt{3}$ phase current

$$(\sqrt{3} = 1.73)$$

$$\text{Power} = \sqrt{3} V_L I_L \cos \phi$$

iii) Line currents are 120° apart

iv) line currents are 30° behind the respective phase current

v) Angle b/w line current & corresponding line voltage ($30^\circ + \phi$) with current lagging.



Star :

- i) line voltages are 120° apart
- ii) line voltages are 30° ahead of their respective voltage.

iii) The angle b/w line current and corresponding line voltage (30°) with current lagging.

iv) Line current = phase current

v) ~~line current~~ voltage = $\sqrt{3}$ phase voltage.



Battery

Primary cell

Lead acid

+ve plate PbO_2 (Anode).

-ve plate Pb (Cathode).

electrolyte \rightarrow Sulphuric acid
 H_2SO_4

30% acid + 70% water
by volume.

Separators: fibreglass, rubber ions
other insulating material.

OCV 2.2V

CCV 2V

Incase of spillage \rightarrow cleaning
bicarbonate of soda.

Specific gravity \rightarrow by using hydrometer
highest = 1.3 - 1.275
medium = 1.275 - 1.240
low = 1.240 - 1.200

Neutralizing agent:

- NaHCO_3 bicarbonate of soda.
- usually constant voltage.
- quick constant current
- No correction necessary.

white charging \rightarrow
Generally constant voltage.
Rapidly - " current.

Ni-cd

+ve $NiO \cdot OH$ (Nickel hydroxide)

-ve cd (Cadmium)

KOH

electrolyte - potassium hydroxide

20-34% conc. electrolyte by weight
70% water by weight

Separators: woven nylon
layer of cellophane.

OCV 1.25V

CCV 1.2V

Incase of spillage
Vinegar or boric acid.

Specific gravity reads by
hydrometer.
SG. 1.3

Neutralizing agent

- Ammonia or boric acid
- usually const + current
- Quick const + voltage.
- white charging \rightarrow

Lead acid battery

- (i) Specific gravity doesn't go beyond using hydrometer
- (ii) Voltage doesn't go beyond level of 2.1V
- (iii) Over gassing in colour. Cathode - chocolate brown, pearl grey
anode - chocolate brown.

Ni-cd:

Specific gravity constant. same
Specific gravity is measured by discharge test

Grid material - lead and antimony.

To correct cell imbalance during reconditioning, the battery is discharged to zero capacity and then recharged it is called deep cycle.

Lead acid:

After charging of the battery
 (+ve plate) - chocolate brown colour
 (-ve plate) - pearl grey colour

In electrodes white powder is formed due to oxidation.

S.G of dil. H_2SO_4 - 1.21 (or near)

cells are connected in series by wire off

Normal - constant voltage
 Quick charging - constant current

expander - prevent loss of porosity

Const. voltage - reduce the time of charge it increase the capacity by app 20% but reduce the efficiency by 10%.

(lead acid) Constant voltage - very low internal resistance

(Ni-cd) Constant current - very high internal resistance, supplies constant current wide range of load resistance.

Ni-cd: Formation of white crystal of potassium carbonate on a properly serviced Ni-cd battery installed in a/c indicates overcharged

cycle
 Voltage remain constant over a major part of discharge
 + First white instantly
 - least for removing
 panel - copper pearl zinc
 Uehlers du - Carbon of zinc
 or Cad

Trickle charging is used for long term storage
It will ensure battery is fully charged condition.
polarization at anode, sulphate @ cathode.

Float charging - method of charging which the
charge and battery are always connected to each other
supply current to load.
Storage of Lead acid - fully charged, if it is discharge sulphation occurs.
" of Ni-cd - fully charged or fully discharge.
Generator:

Value of an induced emf in generator:

- i) No. of wires moving through the magnetic field
- ii) Strength of magnetic field.
- iii) Speed of rotation

Galvanometer - measures current (identified by o at centre)
Compensating windings are connected in series (pole at armature)
embedded in slot of pole faces

Series DC generator not used in a/c

Parallel dc generators used where constant load

Flat compound generators gives constant voltage
on no load and full load.

Armature parallel to field no emf or zero.

" perpendicular to field maximum emf.

Compound generator:

- i) Flat compound - both full load and no load voltage is constant
- ii) Over " - full load \uparrow , no load \downarrow
- iii) Under compound - full load \downarrow , no load \uparrow
- iv) Cumulative - both series and shunt
- v) differential - series opposes shunt.
- vi) shunt compound generator.

Field at armature


Black - neutral
Green - ground

In DC motor, max power } $E_b = V/2$
man. eff. } or half.

Filter: (10-116)


Low pass

Inductance L in series with load
Capacitor C in parallel with load.





High pass

Inductance in parallel with load.
Capacitor in series with load.



Band pass:

Both capacitor & inductor in series with load
" " " " in parallel with load.



Band stop:

Both C & L are in parallel ^{with each other} but series with load
" " " " are series ^{with} each other but parallel with load.

Attenuate: removing frequency:

Decimal System:

~~A filter performate~~ The system of logarithmic measurement is widely used in audio, radio, & all instrument industry for comparing two voltages or current or power level. These levels are measured in a unit called bel (B) or decibel (dB) which is $1/10$ th of a bel.

Active filter: circuit uses operational amplifier w/ DC's

Passive filter: " uses only L, C, R

Cutoff frequency:

The cutoff frequency f_c of the filter is the freq at which the output voltage is reduced to 70.7% of its max value.

A passive filter has attenuation of -3dB at cut of f. freq.

Armature reaction:

distorting and demagnetizing effects will increase with increase in armature current.

(i) demagnetize or weakens the main flux

(ii) cross magnetizes or distorts it.


Magnetic loss is also known as iron loss or core loss

Stray loss = magnetic loss + mechanical loss.

Hysteresis loss:

This loss is due to reversal of magnetisation of armature core.

In armature:



Power factor.

Types of impedance

Phase angle for current

Power factor.

Resistance

0°

1

Inductance

90° lag

0

Capacitance

90° lead

0

R and L

$0 < \phi < 90^\circ$ lag

$0 < PF < 1$ lag

R and C

$0 < \phi < 90^\circ$ lead

$0 < PF < 1$ lead

RLC

b/w 0° and 90°
lead or lag

b/w 0 and unity lead or lag

Comparison of series and parallel resonance:

Item	<u>Series</u>	<u>Parallel</u>
Impedance at resonance	minimum	maximum
Current at resonance	$\max = \frac{V}{R}$	$\max = \frac{V \omega R}{\omega^2 L^2 + R^2}$
Effective impedance	R	L/CR
Power factor at resonance	unity	unity
Resonant frequency	$\frac{1}{2\pi\sqrt{LC}}$	$\frac{1}{2\pi} \sqrt{\frac{1}{LC} - \frac{R^2}{L^2}}$
It magnifies	voltage	Current
Magnification is	$\frac{\omega L}{R}$	$\frac{\omega L}{R}$

Active filter: circuit uses operational amplifier w/ op-amp's

Passive filter: " uses only L, C, R

Cutoff frequency:

The cutoff frequency f_c of the filter is the freq at which the output voltage is reduced to 70.7% of its max value.

A passive filter has an attenuation of -3dB at cut of f. freq.

Armature reaction:


Distorting and demagnetizing effects will increase with increase in armature current.

- (i) demagnetize or weakens the main flux
- (ii) cross magnetizes or distorts it.

Magnetic loss is also known as iron loss or core loss
Stray loss = magnetic loss + mechanical loss.

Hysteresis loss: This loss is due to reversal of magnetisation of armature core.

In armature:



Types of impedance	Phase angle for current	Power factor
Resistance	0°	1
Inductance	90° lag	0
Capacitance	90° lead	0
R and L	$0 < \phi < 90^\circ$ lag	$1 > PF > 0$ lag
R and C	$0 < \phi < 90^\circ$ lead	$1 > PF > 0$ lead
R L C	b/w 0° and 90° lead or lag	b/w 0 and unity lead or lag

Comparison of series and parallel resonance:

Item	<u>Series</u>	<u>Parallel</u>
Impedance at resonance	minimum	maximum
Current at resonance	$max = \frac{V}{R}$	$max = \frac{V \omega R}{\omega^2 L^2 - R^2}$
Effective impedance	R	L/CR
Power factor at resonance	unity	unity
Resonant frequency	$\frac{1}{2\pi\sqrt{LC}}$	$\frac{1}{2\pi\sqrt{\frac{1}{L^2} - \frac{R^2}{L^2}}}$
It magnifies	voltage	Current
Magnification is	$\frac{\omega L}{R}$	$\frac{\omega L}{R}$

Effective or RMS value, $V_{rms} = 0.707 \times V_p$

Peak value, $V_p = 1.414 \times V_{rms}$

Average value of current = $0.63 \times$ max value.

Apparant Power (S) = RMS Voltage \times RMS current
(VA)
 $S = I^2 Z$

Active power (P or W) :

The power which is actually
disipated in a circuit resistance.

unit: watts.

$$P = I^2 R = VI \cos \phi.$$

Reactive power: (Q)

Power developed in inductive circuit.

$$Q = VI \sin \phi$$

Unit - VAR voltamp reactive.

Power Factor = $\frac{\text{True power}}{\text{apparant power}}$

$$PF = \frac{\text{Resistance}}{\text{impedance}}$$

PF = cosine of angle of lead or lag.

AC is more dangerous than DC
($1.414 \times \text{RMS}$).

Alternator BLT-2-1425.

(i) Armature reaction unity (i) power factor
Cross magnetizing flux.
(mainly secondary with distortion)

(ii) Armature reaction of alternator at lagging zero power factor:

Purely demagnetize and armature flux directly weakens main field flux, current more in armature

(iii) The armature reaction of an alternator will be completely magnetizing when load power factor is zero leading (capacitor)



Load and terminal voltage inversely prop

BLT-2
1425

Alternator on load: as load increase terminal voltage decre.

- (i) Armature resistance
- (ii) Armature leakage reactance
- (iii) Armature Reaction

Form factor: $\frac{\text{Ratio of RMS value}}{\text{average value}} = \frac{0.707}{0.637} = 1.11$

Permanent magnets have high reluctance, high coercive force

Battery low internal resistance, no load voltage, will be greater than on load voltage.

Core loss is always constant.

Part Battery covered in hydrogen during polarization
Anode.

built upon cathode sulphation.

Ac motor

Induction:

Le parts.

Single phase - Not self starting, cannot change direction

Shaded pole - Inductor is used

half portion is wound.

It has salient poles.

advantage:

Self starting but very low starting torque.

disadvantage:

Cannot change direction.

low starting torque

very little overload capacity

low efficiency

low power factor.

Split phase: Capacitor is used

Capacitor gives lead effect by 90° (phase shift)

Centrifugal switch - when the motor rpm attained 25% of rated speed, centrifugal switch automatically disconnects.

Capacitor (C.S) is connect with start starting winding,

direction can be changed by interchanging the

leads.

Self starting
each phase 120° apart

high p.f.
very high overload capacity

rotating magnetic field.

by rotating magnetic field torque is produced.

The speed of rotating magnetic field is known as synchronous speed.

Rotor is of squirrel cage type.

Copper or aluminium bars welded to heavy ring of high conductivity on either end.

Due to ~~rot~~ squirrel cage induction motor is self starting.

The speed of rotor is known as non-synchronous speed.

Synchronous speed should never be equal to the non-synch. (if equal motor will not start)

$$\text{Slip} = \frac{\text{Synchro (stator)} - \text{Non-synchro (Rotor)}}{\text{Synchro (stator)}} \times 100\%$$

direction of rotation:

Interchange any two leads, the motor direction will change.

if one broken $\frac{1}{3}$

if two broken $\frac{2}{3}$

3 phase Synchronous motor:

* Single phase synchro. m. used for clocks and other small precision equipment.

Synchro. motor very little starting torque.

It has rotating magnetic field.

Rotor is not of squirrel cage type so it is not self starting.

no slip.

Starting device is used to rotate the rotor up to 90 percent of its stator speed (synchronous speed).

Rotor has a permanent magnet.

generally DC source is given to rotor (AC can also be used)

Alternator

Brushless alternator - No brushes so no arcing,

No sparking at high altitude less maintenance.

It has 3 parts - pilot exciter, exciter and main

generator assembly (Cryden)

Alternator - rated in kVA

i) Pilot exciter - mounted on the main generator rotor shaft and is connected in series with main generator field. It is rectified and controlled.

ii) Exciter - permanent magnets mounted on the main generator stator between the exciter poles. It provides stability, voltage correction, temperature correction. Thermistor is used in the

mech to electrical.

principle - electromagnetic induction:

motor

(torque)

generator.
emf is zero at parallel. (↑)

(torque)

emf is maximum at perpendicular.

dc generators 3 parts.

dc motor 4 parts.

Yoke is also known as field frame.

Purpose of yoke

(i) Protection

(ii) It completes magnetic circuit b/w poles.

Both electromagnet and permanent magnet.

Advantage of electromagnet.

* In electromagnet, the magnetic

property (field) can be increased or decreased.

* If we need more magnetic property (field)

than the perm. magnet, will be very large but in case of electromagnet it is not like this.

Armature:

It is used as an iron conductor in mag. field

Armature should be laminated to prevent eddy current.

Two types:

(i) Gramme ring (not used because it cuts few lines of flux and very low voltage induced)

(ii) drum type (mostly used)

Armature winding are placed in the

slots in the drum type.

drum type cuts more mag. field.

Lap winding is used for high current

Wave winding is used for high voltage.

Commutator:
flexible braided, copper conductor called pig tail.
Connect brush to external circuit.

• AC to DC
mica insulation to a depth equal to width of mica
0.020 inch

Armature reaction:

reduce the main field
distorts the magnetic field.

Compensating windings: neutralize the cross magnetic effect.

Interpoles: reduce sparking - primary purpose.

cancellation of cross magnetisation - secondary purpose

Shape of brushes - rectangular.

Brush spring tension 32-36 ounce.

Commutator pressure $1\frac{1}{2}$ to $2\frac{1}{2}$ psi

Brush - carbon graphite, lite metalized.

DC Generator

Series - Not used in A/c

few turns of large wire

parallel:

many turns of small wire.

Constant voltage.

Compound:

Used where voltage regulation is of prime importance

DC motor

high starting torque at variable speed
engine starting, hoisting gear, A/c motor
few turns of heavy wire.

Low starting torque

Low speed.

Series winding may
either aid shunt or
oppose the shunt winding

Cumulative : Variable speed

It is used for driving machines subj sudden change in load.

high starting torque. (less than series) (series can't be used easily)

Differential : increase in load, I increases, decreases total flux

man. eff }
man. powe. } back emf, $E_b = \frac{V}{2}$

Intermittent duty - short period - 2min or less than
Continuous " - long " - more than 2min

Cu loss @ full load = Cu loss @ half or no load / 4

Capacity of battery depends upon.

- (i) Rate of discharge
- (ii) Temperature
- (iii) Density of electrolyte
- (iv) Quantity of active material.

Does not depend upon rate of charge.

Squirrel cage rotor:

Skewed rotor slots: (It does not give starting torque)

* (i) It helps to make motor run quietly by reducing the magnetic hum and.

(ii) It helps in reducing the locking tendency of rotor i.e. the tendency of the rotor teeth to remain under the stator teeth due to direct magnetic attraction b/w two.

Lap winding - $\text{Wg. current} \div \text{No. of poles} = \text{No. of brushes}$
wave winding = high voltage $\div \text{No. of poles} = \text{No. of brushes} - 2$

Slip in synchro motor @ Start 100%
 @ running 0%


1 coulomb of charge intensity of force $9 \times 10^9 \text{ N}$

absolute permittivity Farad/meter.

In sphere (charged conducting) zero is electric intensity

" " " " " " potential is constant

$$\text{One farad} = \frac{\text{one coulomb}}{\text{one volt}} = \frac{a}{v}$$



(n-1) (n+1)

no. of plates (n+1) c

no. of capacitors (n-1)

Active component - having its own power source.

passive component - no own power.

Vacuum
 Air

$$\mu_0 = 4\pi \times 10^{-7} \text{ H/meter}$$

$$\mu_r = 1$$

$\mu_0 = 0$ for air and

μ_r has no unit

permittivity - ϵ_0

$$\epsilon = \epsilon_0 \epsilon_r \text{ (R.P.)}$$

$$\epsilon_0 = 8.854 \times 10^{-12} \text{ C/m}$$

$$\epsilon_r = 1$$

permeability

$$\mu = \mu_0 \mu_r \text{ (R.P.)}$$

$$\mu = \mu_0$$

$$\mu_0 = 4\pi$$

Incoming $I =$ ~~out~~ going current $\cdot V$

$$I_{in} I - Out I = 0$$

K. Voltage law (closed circuit)

applied - algebraic sum of applied voltage drop = 0

applied voltage = algebraic sum of voltage drop.

High stability - wirewound resistor.

Carbon resistor - noise.

5th band - temperature coefficient and reliability.

Gold in third band $\frac{10}{100}$

Silver in " " $\frac{1}{100}$

Gold in fourth band 5%

Silver in fourth band 10%

Inductors: cross sect area increase inductance incre

radius double ~~cross~~ inductance 4 -

FOR ANY MODULE HELP
CONTACT

WORLD'S OF AME

RUTVIK:-6353932311

SUNNY:-6353840573

Armature reaction :-

Dis-advantage:

- ✓ It demagnetises (or) weakens the main flux.
- ✓ It cross magnetises (or) distorts it.

① In DC generator, armature reaction is produced actually by:

- a) its field current.
- b) Armature conductors.
- c) Field pole winding.
- d) load current in armature.

② In a DC generator, the effect of armature reaction on the main pole flux is to,

- a) reduce it.
- b) distort it.
- c) reverse it.
- d) both (a) & (b).

③ The primary reason for providing compensating winding in DC generator is to:

- a) compensate for decrease in main flux.
- b) neutralize armature MMF.
- c) neutralize cross magnetising flux.
- d) maintain uniform flux distribution.

④ The most likely causes of sparking at the brushes in DC machine is:

- a) open coil in armature.
- b) defective interpoles.
- c) incorrect brush spring pressure.
- d) All the above.

⑤ The commutation process in DC generator basically involves

- a) passage of current, from moving armature to a stationary level.

b) Reversal of current in an armature coil as it crosses M.P.A.

c) conversion of AC to DC.

d) suppression of reactance voltage.

① If the residual magnetism of shunt generator is destroyed accidentally, it may be restored by connecting its shunt field.

a) to each.

b) to an A.C source.

c) in reverse.

d) D.C. source.

② An ideal D.C generator is one that has _____ voltage regulation.

a) low.

b) zero.

c) positive.

d) negative.

③ The _____ generator has poorest voltage.

a) series.

b) shunt.

c) compound.

d) high.

④ what is the best way of minimizing eddy current in an armature lamination.

⑤ what causes sparking at the brushes?

Ans: It is due to self induction of the coil undergoing commutation.

⑥ what are the two kinds of sparking produced in a generator?

Ans: (i) due to bad adjustment of brushes.

(ii) due to poor condition of the commutator.

(7) What causes humming?

- Ans:
- (i) Eddy current.
 - (ii) moisture which almost short circuits the armature.
 - (iii) unequal strength of the magnetic poles.
 - (iv) operation above rated voltage & below normal speed.

Note:

Speed can be controlled by varying?

- * Flux ϕ (Flux control).
- * Resistance of armature circuit (Rheostatic control).
- * Applied voltage (voltage control).

Star connection.

Line current = Phase current.


Line voltage = $\sqrt{3}$ Phase voltage ($\sqrt{3} = 1.73$).

Power = $\sqrt{3} V_L I_L \cos \phi$.

Delta connection.

Line voltage = Phase voltage.

Line current = $\sqrt{3}$ phase current.



AC motor.

Principle. \rightarrow EMI.

Electric to mechanical

In AC motor do not use brush & commutator
Rated by,

- * HP output (1 HP) (746 watt)
- * Full load current
- * operating voltage
- * speed of rotation
- * frequency
- * no. of phases (3 ϕ)

number plate in motor:

- * no. of poles
- * speed of motor

Types of motor:

- (*) Induction motor
- (*) Synchronous " (1, 2, 3 phases on both)

① Induction motor:

✓ squirrel cage motor (made by Al, Cu)

✓ single phase motor.

* pulsating o/p.

* deflection by 180° (3 ϕ)

✓ Shaded poles. (low initial torque) (low eff)

✓ split phase (10-15F)

* switch is off (25% o/p)

* Rate of phase 90°

* running winding - starting winding

- * $\phi = 30^\circ$. * 3-phase \Rightarrow change the $\frac{1}{p}$ lead
- * $\phi = 30^\circ$. * 2-phase \Rightarrow change the (1 phase magnet).
- * 1-phase \Rightarrow change the $\frac{1}{p}$ lead.
- * Shaded poles \Rightarrow It cannot be change.

Synchronous motor :-



- ✓ Rotor winding - DC input.
- ✓ stator winding - AC input.
- ✓ when little load is applied - lag the rotating rotor, then it will start slowly.
- ✓ when high load is applied - opposite it lag, then it will stop rotating (over loaded).

synchronous - induction (rotating field).

- * It has low initial torque (so we use any other mean) then it Remove.
- * synchronous - not a self starting motor.
- * mag field of rotor (lock) mag field of stator.

Frequency, $F = \frac{PN}{120} \rightarrow \text{rpm}$

$I \cdot R = \frac{\text{OCV} - \text{CCV}}{\text{'I' load}}$

Current, $I = \frac{Q}{t}$ - charge

Potential, $E = \frac{\epsilon}{Q}$ - energy

Potential, $V = IR$

Power, $P = \frac{\epsilon}{t}$ - energy - time

$P = VI, I^2R, V^2/R$

Frequency, $F = \frac{1}{t}$ - time

$V_{\text{rms}} = 0.707 \times V_P$ - Peak voltage.

$V_P = 1.414 \times V_{\text{rms}}$

Average value = $0.63 \times \text{max. value}$

$\tau = RC$, τ - time constant

$\tau = \frac{L}{R}$

capacitance, $C = \frac{q}{E}$ - charge - voltage

energy, $E = \frac{1}{2} CV^2$

$C = k \cdot \frac{A}{d}$

$R = \frac{\rho l}{A}$

capacitive reactance, $X_C = \frac{1}{2\pi fC}$

Inductive reactance, $X_L = 2\pi fL$

Inductance, $L = -N \frac{d\phi}{dt}$

$F = NI$

Series,

Impedance, $Z = \sqrt{R^2 + X_L^2}$

$Z = \sqrt{R^2 + (X_L - X_C)^2}$

Parallel,

$Z = \frac{R X_C}{\sqrt{R^2 + X_C^2}}$

Resonant frequency, $f_n = \frac{1}{2\pi\sqrt{LC}}$

P.F = $\frac{\text{True Power}}{\text{Apparent Power}}$

P.F = $\frac{\text{Resistance}}{\text{Impedance}}$

P.F = cosine of angle lead or lag.

Apparent Power = $I^2 Z$

" = Rms voltage x Rms current

Active power } = $VI \cos \phi$
 True " }
 Real " } (P.F)

Reactive power = $VI \sin \phi$

Transformer, $\frac{E_1}{E_2} = \frac{N_1}{N_2} = \frac{I_2}{I_1}$

wheatstone, $R_x = \frac{R_1}{R_2} \times R_3$

mmf = $I \times N \rightarrow \text{turns}$

$B = \frac{\phi}{A}$ current

magnetising force, $H = \frac{\text{mmf}}{l} = \frac{IN}{l}$

Permeability, $\mu = \frac{B}{H}$ - flux density

slip = synchronous - non synchronous

Potential - volt (V)

Emf (E) - volt (V)

Current (I) - Ampere (A)

Resistance (R) - ohm (Ω)

Resistivity - ohm-meter (Ωm)

Power (P) - watt (W)

Frequency } - Hertz (Hz)
Resonance }

Inductance (L) - Henry (H)

Capacitance (C) - Farad (F)

Charge (Q) - coulomb (C)

Energy (E) - Joule (J)

Impedance (Z) } - ohm (Ω)

Inductive reactance (X_L) }

Capacitive reactance (X_C) }

Magnetic flux (ϕ) - weber (W_b),
maxwell

flux density (B) - Tesla (T)

mmf = Ampere turn, (At)
gilbert

Reluctance - Ampere turn / weber,
gilbert / maxwell.

Field intensity } - gauss
flux density } / coulomb

work - Joule, kilogram metre force

electrical pressure - volt.

magnetising force (H) = $\frac{At}{m}$ - metre

Permittivity (ϵ_0) - F/m

Permeability (μ) - No unit.
 $\mu_0 = H/m$

slip - percentage (%)

conductance (G) - siemen

conductivity - siemen/metre

wavelength (λ) - metre (m)

Apparent power (S) - volt-amp

Active power (P or W) - watts.

Reactive power (Q) - volt-amp-reactive
(VAR)

Electric intensity - N / coulomb
Volt / metre

Power level } decibel
Attenuation }

Inducton.
No. of turns of current in core, \propto
flux.

WORLD'S OF AME